

ATTACHMENT A

**SHIRLEY SEPTIC PUMPING FACILITY
JULY 13, 2023
INSPECTION PHOTOS TAKEN BY THE DIVISION**



Photo 1: Shaker screen used to remove debris from septage.



Photo 2: Bin for collection of debris screened from incoming septage.



Photo 3: First frac tank that receives septage after pH adjustment and screening.



Photo 4: Dewatering unit, manufactured by In the Round Dewatering.



Photo 5: Second frac tank next to dewatering unit.



Photo 6: Solids stored behind the dewatering unit.